






GND 3010
Above the top Irrigation Block




GND 2188
Between the two Top Irrigation blocks




GND 2189
Below Irrigation Area G




GND 3009
Below Duck Pond




GND 2190
Next to Irrigation Area I











GND 3008
Below bottom Irrigation Block










GND 3007
SH 3










**Surfacewater Sampling up to:
May 2020**










**HHG 97
Above the Wetland**










**HHG 103
Below the Wetland**










**HHG 115
Below the Main Composting Pad - Duckpond**



**HHG 150
Twin Culvert**



**HHG 190
Upstream of SH3 Bridge**



Water in


Below the Wetland

Below the main Composting Pad

Twin Culvert

Water leaving property

Soil Sampling up to:
12/04/19



Soil Sampling
SOL 177
Lower irrigation block
Irrigation areas H & J

SOL 176
Upper irrigation block

SOL 193
Irrigation block E (?)

SOL 1
Irrigation block X

SOL S2
Irrigation block X

